SECRET

OUT55126

COPIES RECEIVED

Office

ADMIN

CsD IPD

PSJ TID

PAG CIA/PID

DIAXX-4

NSA LO

SEC BR P&Ds

Master File

CyNo.

Declassification Review by NGA/DoD

S E C R E T 251820Z

1965 FEB 25 18 36 Z

25X1

Act.

1. CAMERA B 101 WAS USED IN MISSION 3991 FLOWN ON 23 FEBRUARY

1965. PROCESSING WAS ACCOMPLISHED BY NAV RECON TECH SUPPCEN.

- 2. ORIGINAL NEGATIVE:
 - A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD.
- B. 9R SIDE: SLIGHT EDGE F G IS PRESENT ALONG BOTH EDGES
 THROUGHOUT THE MISSION. MIN OR EDGE STATIC OCCURS ALONG THE OUT
 BOARD EDGE DURING THE FIRST 500 FRAMES OF THE MISSION. PLUS
 DENSITY S.REAKS, PARALLEL TO THE MAJOR AXIS OF THE FILM, CCUR
 INTERMITTENTLY THROUGHOUT THE MISSION. MANUFACTURING SPLICES A REPRESENT ON FRAMES 646 AND 1840. A HEAT SPLICE IS PRESENT ON FRAME
 1189. FOGGED AREAS EFFECT FRAMES 2251 AND 2252.
- C. 9L SIDE: THE FIRST 100 FRAMES CONTAIN EDGE FOG ALONG

 Destroyed
 THE INBOARD EDGE. THERE IS A FLARE ADJACENT TO THE DATA CHAMBER
 THROUGHOUT THE MISSION. THERE ARE A SERIES OF PLUS DENSITY
 LINES THAT ARE PARALLEL TO THE MAJOR AXIS OF NEGATIVES. FIVE
 ARE MORE PROMINENT AND LIE 2.5, 4.6, 5.0, 5.2 AND 5.4 INCHES
 FROM THE INBOARD EDGE. THE LINES TERMINATE AT THE HEAT SPLICE
 IN FRAME 1111 AND A NEW SERIES OF LINES ARE PRESENT THAT MEASURE
 1.6, 3.2, 4.8, 6.4 AND 8.0 INCHES FROM THE INBOARD EDGE. WITH THE
 EXCEPTION OF THE ONE THAT IS 1.6" FROM THE INBOARD EDGE THE LINES
 GRADUALLY DIMINISH UNTIL THEY ARE NO LONGER DETECTABLE (FRAME
 1251). THE LINE THAT IS 1.6" FROM THE EDGE IS PRESENT FOR THE

SECRET

GROUP 1
Excluded from autom25X1
flowingrading and declassification

BALANCE OF THE MISSION. FRAME 1112 CONTAINS SCUM AND HANDLING MARKS. AN ISQLATED WAVERING MINUS DENSITY STREAK OF UNDETER-MINED ORIGIN IS LOCATED Ø.5" FROM THE INBOARD EDGE IN FRAME 587.

FRAME 1904 CONTAINS A MANUFACTURING SPLICE.

- D. BOTH SIDES: A FEW IS CLATED FRAMES CONTAIN SMEARED IMAGERY (52, 792, 1324, 1722, 19.6) THAT CAN BE ATTRIBUTED TO VEHICLE RATE ATTITUDE. AN APPARENT CAMERA MISLATCH OCCURRED AT COUNTER FRAME 1571 WHEN THE CAMERA DID NOT GO TO POSITION 2L BUT RECORDED A SEC OND FRAME IN THE 1R POSITION. THE CAMERA THEN RETURNED TO V (FRAME 1572) AND FAILED TO RECORD OR METER FILM FOR FRAME 1573. IT REMAINED IN THE VERTICAL POSITION AND RECORDED ANOTHER V (FRAME 1574) AND THEN OPERATED PROPERLY FOR THE BALANCE OF THE MISSION. THE VEHICLE WAS IN A 90 DEGREE TURN DURING THIS MISLATCH AND THE CYCLE RATE DOES NOT INDICATE THAT THERE WAS A CAMERA OFF.
- E. THE TITLED FRAMES ARE NUMBERED 0001 TO 2348. THE COUNTER FRAMES ARE NUMBERED 0001 TO 2349 WITH NO FRAME 1573.
 - 3. POSITIVE:
 - A. PI SUITABILITY IS GOOD.
 - B. PRINTING AND PROCESSING ARE GOOD.
- C. CLOUDS OBSCURE 20 TO 25 PERCENT OF THE MISSION.
 SECRET

-END OF MESSAGE-